

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

F-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th Mer.

CN (# 2) 1/16 Corner common to Sections
-----, -----, 11, and -----

Corner consists of a 4" ash (not) in place
State condition good (1" iron pipe 6")

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 2		# 2	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

# 2 S. 11			
B.T			

Species ASPEN

Diameter 8"

Bearing N 39° W

Distance 4 1/2 li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Erwin Meagher
(Signature)

12-7-34
(Date)

Field ass't
(Title)

F-19

LAND level, Mixed
Hard Woods

Corner again.

Give any further facts which will aid in finding this

tree ~~is~~ distant.

from which this Corner bears


S. 39° E

side of tree

tree 8 inches diameter, on the

S.E

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 474 Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST F 19

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

2 1/16 Corner common to Sections

.....,, 11, and 2

Corner consists of a 4" ash (not) in place

State condition good (1" iron pipe 6")

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 2		# 2	
S 11		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

# 2 S. 11			
B.T.			

Species aspen

Diameter 8"

Bearing N 39° W

Distance 4 1/2 Li

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

Emin Meagher

(Signature)

12-7-34

(Date)

Field ass't

(Title)

LAND LEVEL, MIXED
HARD WOODS

Corner again.

Give any further facts which will aid in finding this

4 1/2 L. chains distant.

From which this Corner bears


S 39. E

side of tree

tree 8 inches diameter, on the

S. E

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4 1/2 Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

F-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

NE (# 2) 1/16. Corner common to Sections
_____, _____, _____, and _____

Corner consists of a 4" ash (not) in place
State condition good (1" iron pipe 6")

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

# 2 S. 11		# 2 S. 11	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

# 2 S. 11			
B.T.			

Species ASPEN

Diameter 8"

Bearing N 39° W

Distance 4 1/2 Li

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

Erwin Meagher

(Signature)

Field Ass't

12-7-34

(Date)

(Title)

f-19

LAND Level, MIXED HARD WOODS

Corner again.

Give any further facts which will aid in finding this


4 1/2 in. ~~chairs~~ distant.

From which this Corner bears 539.0 E

side of tree

tree 8 inches diameter, on the S E

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.