

U. S. Department of Agriculture

FOREST SERVICE

Posted H 21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

S 416 Corner common to Sections 11, and 12

Corner consists of a 3" ASPEN (now) in place State condition good

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	11		12

N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Emin Meagher*  
(Signature)

*12-4-34*  
(Date)

*Field Ass't*  
(Title)

CORNER IS ON FENCE LINE  
 RUNNING E & W  
 ALSO CORNER IS IN LARGE  
 OPEN SIMILAR PITS  
 E & W

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

11-27  
 A-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

S 116 Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 11, and 12.

Corner consists of a Aspen (not) in place  
 State condition good

Dimensions above ground 2' high inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	11		12
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

Erwin Menger  
 (Signature)  
12-4-34 Field aspen  
 (Date) (Title)

12-7

No. place for poster

CORNER IS ON FENCE LINE  
RUNNING E.W. AND  
IN A LARGE OPEN  
SWAMP Drs E-W

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

**U. S. Department of Agriculture**  
**FOREST SERVICE**

H-21

*Chippewa* NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 57 N R. 26 W 4th Mer.

----- S. 1/4 Corner common to Sections  
-----, -----, 11, and 12

Corner consists of a 3" ASPEN (tree) in place

State condition good

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	11	-	12

N      W      S      E

-			

NW    SW    SE    NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

-----

-----

-----  
*Erwin Hughes*

(Signature)

12-4-34  
(Date)

Field ass't  
(Title)

12-2

No place for poster

CORNER IS ON FENCE LINE  
RUNNING E-W AND  
IN A LARGE OPEN  
SWAMP BRD E-W

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.