

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57-58 R. 26-25 4th Mer.

A-25

Township Corner common to Sections  
1, 6, 31, and 36

Corner consists of a Tan. stake in place  
State condition good

Dimensions above ground 5x6x24 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

S 36	S 1	S 6	S 31
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_  
Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T.58N. R.27W. S.36	T.58N. R.27W. S.36		
BT	BT		

Species Spruce Tan. stubl 4' high Spruce  
Diameter 9" 6" 6"  
Bearing N24°30'W. N21°E. S38°W.  
Distance 94 lk. 50 lk. 69 lk.

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? Stake and BT's are not original.  
However, I found what I believe to be a  
piece of original stake buried in pre-  
sent location.

(Signature)

9/1/37

(Date)

Jr. Assist. to Tech.

(Title)

A-25

Corner is in swamp ground containing spruce, birch, aspen, & cedar.

Corner again.

Give any further facts which will aid in finding this


0.25 chains distant.

from which this Corner bears

side of line

tree 5 inches diameter, on the north

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

A-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57-58 R. 26-27 4th Mer.

Township Corner common to Sections 1, 6, 31, and 36

Corner consists of a Tan. stake Iron pipe in place State condition good

Dimensions above ground 5 1/2 x 2 1/4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Table with 4 columns labeled N, W, S, E

Table with 4 columns labeled NW, SW, SE, NE containing numbers 36, 1, 6, 31

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Table with 4 columns for T56N, R27N, S.36, BT and 4 empty boxes for T.56N, R.27N, S.36, BT

Species Spruce Ten. stub 4' high Spruce Diameter 9" 6" 6" Bearing N24°30'W N21°E S38°W Distance 94 lk. 50 lk. 69 lk.

Do you believe this to be a genuine Land Office Corner? Yes If not, why? Stake and BT's are not original However, I found what I believe to be a piece of original stake buried in present location.

(Signature)

9/1/37

(Date)

Jr. Assist. to Tech.

(Title)

A-25

Corner is in swamp ground containing spruce, birch, aspen, & cedar.

Corner again.

Give any further facts which will aid in finding this


0.25 chains distant.

from which this Corner bears 156° E

side of line

tree 5 inches diameter, on the north

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)