

U. S. Department of Agriculture  
FOREST SERVICE

2-10-21

CHIPPewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4 Mer.  
M.C. Corner common to Sections

....., ....., 1, and 2  
Corner consists of a 4" ASPEN (net) in place  
State condition good

Dimensions above ground 36 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

	S		S
	2		1
N	W	E	

DIAGONAL POSITION

NW	SW	SE	NE

Mound of ..... is located .....

..... Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S		S
	2		1
	BT		BT

Species ASPEN W. Birch  
Diameter 8" 9"  
Bearing N 40° W N 70° E  
Distance 15 Lks 9 Lks

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? .....

Ervin Molyher  
(Signature)

10-21-24  
(Date)

Field Agent  
(Title)

C-0-21

ON BANK OF JOHNSON LAKE

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears S 73° E

side of Tree

tree 9 inches diameter, on the SE

Metal Location Poster is on a N. 15° E



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

C-D-21

Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4<sup>th</sup> Mer.

M. C. Corner common to Sections

....., ....., 1, and 2.....

Corner consists of a 4 in. aspen (net) in place

State condition good

Dimensions above ground 3 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	2		1

N W S E


NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S		S
	2		1
	B.T.		B.T.

Species ASPEN W. BIRCH

Diameter 8 in. 9 in.

Bearing N 70° W N 73° E

Distance 15-1 Ks 9-1 Ks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? .....

Erwin Meagher

(Signature)

10-31-34

(Date)

Field Ass't

(Title)

C-0-21

M.C. JOHNSON N. BANK  
of JOHNSON LAKE

Corner again.

Give any further facts which will aid in finding this


9-ftts chains distant.

from which this Corner bears S. 73° E

side of tree

9 inches diameter, on the S. E

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4-44 Mer.