

U. S. Department of Agriculture
FOREST SERVICE

Posted
E 17-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

----- M.C. Corner common to Sections
-----, -----, 2, and 11-----

Corner consists of a 4" aspen post (not) in place
State condition good 3/4" iron pipe.

Dimensions above ground post 30" pipe 10 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 2		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 2		S 11	
B.T.		B.T.	

Species aspen ----- aspen stump -----
Diameter 7" ----- 8" -----
Bearing N. 89° E ----- N. 14° W. -----
Distance 28 links ----- 40 links -----

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Ernest Perry
(Signature)
Field ass't
(Title)

10-30-34 -----
(Date)

Corner again.

Give any further facts which will aid in finding this


Blinks ~~beats~~ distant.

from which this Corner bears *S. 89° W.*

side of *tree*

tree *7* inches diameter, on the *S.W.*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

E-17-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N. R. 26W. 4th Mer.

M.C. Corner common to Sections
2, and 11

Corner consists of a 4" aspen post (not) in place
State condition good 3/4" iron pipe

Dimensions above ground post 30" pipe 10 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S R		S 11	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S R		S 11	
B.T.		B.T.	

Species aspen aspen stump
Diameter 7" 8"
Bearing N. 89° E. N. 14° W.
Distance 28 links 40 links

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____

Ernest Perry
(Signature)

Field ass't.
(Title)

10-30-34
(Date)

E-17-18

Corner again.

Give any further facts which will aid in finding this


~~28 links chains distant.~~

from which this Corner bears S89°W

side of tree

tree 7 inches diameter, on the SW

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

E-17-18

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 57N. R. 26W. 4th Mer.

M.C. Corner common to Sections

....., R., and 11

Corner consists of a 4" ASPEN POST (not) in place

State condition good 3/4" iron pipe

Dimensions above ground post 30" pipe 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S. R		S. 11	
---------	--	----------	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. R		S. 11	
B.T.		B.T.	

Species aspen aspen stump

Diameter 7" 8"

Bearing N. 89° E N. 14° W

Distance 28 links 40 links

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Ernest Perry

(Signature)

Field Asst.

(Title)

10-30-34

(Date)

E-17-18

Corner again.

Give any further facts which will aid in finding this


2.8 links ~~chains~~ distant.

from which this Corner bears 589° W.

side of tree

tree 7 inches diameter, on the S.W.

Metal Location Poster is on a *aspen*



(Make sketch of topography near Corner)

T. 52N R. 26W Mer. 4th