

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST *E 19-20*

CORNERS OF THE PUBLIC SURVEY

T. *57* R. *26* Mer. *4*

*Meander* Corner common to Sections  
*2*, and *11*

Corner consists of a *Wooden Stake* (not) in place  
*+ Iron Pipe*  
State condition

Dimensions above ground *4x4x24* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>Mc</i>		<i>Mc</i>	
<i>5</i>		<i>5</i>	
<i>2</i>		<i>11</i>	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter *No. B. T.*

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_


*Clarence B. Chase*  
(Signature)

*11/27/33*  
(Date)

*Computer*  
(Title)

Metal Location Poster is on a tree ..... inches diameter, on the side of ..... from which this Corner bears ..... chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)