

U. S. Department of Agriculture

FOREST SERVICE

Posted.

Chippewa NATIONAL FOREST 620-21

CORNERS OF THE PUBLIC SURVEY

T. *57 N* R. *26 W* *4th* Mer.

M. C. Corner common to Sections
 _____, _____, *11*, and _____

Corner consists of a *4" aspen* (not) in place

State condition *good*

Dimensions above ground *3' high* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>M</i>		<i>M</i>	
<i>C</i>		<i>C</i>	
<i>S 11</i>		<i>S 11</i>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>M</i> <i>S C 11</i>		
	<i>BT</i>		

Species *aspen*

Diameter *6"*

Bearing *S 56° W*

Distance *2 li.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

E. M. Meagher
 (Signature)

12-6-34
 (Date)

Field Ass't.
 (Title)

Land level, second growth aspen

Corner again.

Give any further facts which will aid in finding this


9 1/2 chains distant.

From which this Corner bears N 56° E

side of trees

tree 6 inches diameter, on the N E

aspen Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

G-20-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.



M.C. Corner common to Sections
.....,, 11, and

Corner consists of a 4" ASPEN (not) in place
State condition good

Dimensions above ground 3' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASPEN
Diameter 6"
Bearing S56° W
Distance 9 li

Do you believe this to be a genuine Land Office Corner? yes
If not, why?

Emin Meagher
(Signature)
Field Ass't
(Title)
12-6-34
(Date)

6-20-21

LAND Level, Second
growth ASPEN

Corner again.

Give any further facts which will aid in finding this


9 L. ~~chairs~~ distant.

from which this Corner bears N56°E

side of tree

tree 6 inches diameter, on the N.E

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

G-20-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

M.C. Corner common to Sections
-----, -----, 11, and -----

Corner consists of a 4" ASPEN (not) in place
State condition good

Dimensions above ground 3' high inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M C S 11		M C S 11	
N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	M C S. 11		
	B.T.		

Species ASPEN

Diameter 6"

Bearing S 56° W

Distance 9 1/2'

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

Emin Meagher
(Signature)

12-6-34
(Date)

Field Ass't
(Title)

6-20-21

Land level, second growth aspen

Corner again.

Give any further facts which will aid in finding this


971. chains distant.

from which this Corner bears N 56° E

side of TREE

tree 6 inches diameter, on the NE

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.