

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

J-18-19

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

..... M. C. Corner common to Sections
,, 11, and 14

Corner consists of a 9 ASPEN (not) in place
 State condition good

Dimensions above ground 2' 6" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M C 511		M C 514	
N	W	S	E

NW	SW	SE	NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	M. C. S 14		
	B. T.		

Species W. PINE
 Diameter 12"
 Bearing N 58° W
 Distance 55 Li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Emin Meagher
 (Signature)

12-4-34
 (Date)

Field Ass't
 (Title)

J-18-19

LAND ROLLING CO.
around cor.

Corner again.

Give any further facts which will aid in finding this

55 ft. chains distant.

from which this Corner bears


S 58° E

side of tree

tree 12 inches diameter, on the

W. PINE S.E.

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

J-18-19

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

M.C. Corner common to Sections
11, and 14

Corner consists of a 4" ASPEN (not) in place
State condition good

Dimensions above ground 2'6" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M C S 11		M C S 14	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	M. C. S 14		
	B. T.		

Species W. pine

Diameter 12"

Bearing N 58° W

Distance 55 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Erwin Meagher
(Signature)

12-4-34
(Date)

Field ass't
(Title)

6-18-19

LAND ROLLING, B. C.
ALOUND COR.

Corner again.

Give any further facts which will aid in finding this


55 L. chains distant.

from which this Corner bears S. 58° E.

side of tree

tree 1/2 inches diameter, on the

Metal Location Poster is on a W. PINE S.E.



(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST J 18-19

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

MC Corner common to Sections
11, and 14

Corner consists of a 4" ASPEN (not) in place
State condition good

Dimensions above ground 2' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 11		S 14	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 14
			B.T

Species _____ N. Pine
Diameter _____ 10"
Bearing _____ S 72° E
Distance _____ 38 Li

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Ernie M. Meyer
(Signature)

12-4-34
(Date)

Field Ass't
(Title)

LAND ROLLING
LITTLE BIG HORNTAIL
IS AVE CHANS E. OF
COR. LAKE BRS N-W
AND S-E
Corner again.

Metal Location Poster is on a
tree 10 inches diameter, on the
side of tree
from which this Corner bears
38 L^{ts} about distant.
Give any further facts which will aid in finding this
Corner again.



(Make sketch of topography near Corner)

T. 57N R. 26W 9th Mer.