

U. S. Department of Agriculture
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

K 16-17

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4 th Mer.

Special Meander Corner common to Sections 15

Corner consists of a 2" scribed post and 5" Iron Pipe in place

State condition Good

Dimensions above ground Post 24" Pipe 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M.C. S. 15		M.C. S. 15	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C. S. 12	M.C. S. 12		
B.T.	B.T.		

Species W. Pine W. Pine

Diameter 14" 20"

Bearing S78°E N20°E

Distance 38 Lks 50 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor.

Arthur Johnson
(Signature)

11/23/39

(Date)

Squad Foreman

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.