

U. S. Department of Agriculture
FOREST SERVICE

N-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 27W 4th Mer.

E 1/16 Corner common to sections
13, and 24

Corner consists of a _____ (not) a place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Elm Elm Stump _____

Diameter 12" 14" _____

Bearing S38°E N61°E _____

Distance 53 lks 105 lks _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Record shows it was set by County Surveyor

Arthur J. Johnson

(Signature)

Equal Foreman

(Title)

2/8/90

(Date)

N-24

Root 31/2 section center of road
of road

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 52N R. 27W 475 Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST No. 24

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 27W 9th Mer.

E 1/4 Corner common to Sections
13, and 29

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Elm Elm Stump

Diameter 12" 19"

Bearing S 20° E N 61° E

Distance 53 lks. 105 lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by
County Surveyor.

Arthur J. Johnson

(Signature)

Agent Foreman

(Title)

2/18/40

(Date)

Post should set in center of Road.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 52N R. 22W 9th Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

h-2-N

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 27W 4th Mer.
E. 1/16 Corner common to Sections
 _____, 13, and 29

Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B. T.			

Species Elm Elm Stump
 Diameter 12" 14"
 Bearing S38°E N61°E
 Distance 531ks. 1051ks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by
County Surveyor.

Arthur J. Johnson
 (Signature)

Squad Foreman
 (Title)

2/8/19
 (Date)

N-24

Post show well in center of road.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 27W 97th Mer.