

U. S. Department of Agriculture
FOREST SERVICE

E-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 & 27 W. 4th P. Mer.

Section Corner common to sections

1, 6, 7, and 12

Corner consists of a Cedar post & iron pipe

State condition good

Dimensions above ground pipe $\frac{1}{2}$ x 6, post $3\frac{1}{2}$ x 3 $\frac{1}{2}$ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--------------------|-----|---------------------|---------------------|
| 3.1 T57N R27 | S12 | S.7 T57N R26W | S.6 T57N R26W |
|--------------------|-----|---------------------|---------------------|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T57N
R26W
S 6

6
W
S

No scribing
discernable

Species Cedar Cedar Ash Ash stump
 Diameter 12" 12" 18" rotten
 Bearing N33° E S85° E S74° E N64°
 Distance .24 ch. .19ch .36ch .27ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

[Handwritten Signature]

(Signature)

2/11/38

(Date)

JR. Assist. to Tech.

(Title)

E-21

Corner is on SW edge of cedar swamp
just at bottom of steep ridge.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.36


from which this Corner bears

N74°E

side of

tree 18 inches diameter, on the

Metal Location Poster is on a
Neb Bearing



(Makes sketch of topography near Corner)