

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST J1  
CORNERS OF THE PUBLIC SURVEY

T. *58 N.* R. *25 & 26* 4<sup>th</sup> Mer.

Section *17* Corner common to Sections  
*12, 13, 7;* and *18*

Corner consists of a *4 1/4 aspen* in place

State condition *good*

Dimensions above ground *3 feet* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

R. 26	R. 25
S. 12	S. 13
S. 18	S. 7
NW	SW
SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Ervin Meagher*

(Signature)

*9-4-34*

(Date)

*Field Ass't*

(Title)

COR. STAKE IS ON W. side of large dead TAM. SWAMP, NO B.T.

Corner again.

Give any further facts which will aid in finding this


21-LINKS chains distant.

from which this Corner bears N 41° E

side of tree

tree 4 inches diameter, on the

Metal Location Poster is on a ASPEN N.E.



(Make sketch of topography near Corner)

T. 58 N. R. 25 W 4th Mer.