

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

C-18

ch NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer.

CW 1/6 # 9 Corner common to Sections
2, _____, and _____

Corner consists of a pipe (not) in place
State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No

set in 1954 by ?

Ralph H. ...
(Signature)

D. F. R.
(Title)

12-2-54
(Date)

East

Transect line 20075

Corner again.

Give any further facts which will aid in finding this

chains distant.


11 ft

from which this Corner bears North

side of it

tree 4 inches diameter, on the North

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

Mer 2-18

R

T