

U. S. Department of Agriculture
FOREST SERVICE

A-19

Chipp

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *58-59* R. *25* Mer.

7 Corner common to Sections
35 - 2, _____, and _____


Corner consists of a *Iron Pipe-Aluminum cap* (not) in place
State condition *good*

Dimensions above ground *24* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Ash* _____ *Cedar* _____

Diameter *12"* _____ *16"* _____

Bearing *N45E* _____ *S85E* _____

Distance *26FT* _____ *8FT* _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? *No - Est. by county*
1954

Ralph H. Shultz
(Signature)


D. F. P.
(Title)

12-7-54
(Date)

Control Tag on North
Side of Road - 320 ft
from corner south to road.
Corner again.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this

Both B.T.'s



(Make sketch of topography near Corner)