

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer.

Corner common to Sections

13, 14, 23, and 24

Corner consists of a Scribed post (not) in place

State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Cedar Cedar Cedar

Diameter 12" 10" 10"

Bearing E S30W S - estimated

Distance 30' 26' 28' Dist. passed

Do you believe this to be a genuine Land Office Corner? No

If not, why? Not orig. BT.


R. H. Christy
 (Signature)

2-19-57
 (Date)

R. F. R.
 (Title)

Corner again.
 Scrib post leaning against
 about 7500 Road cross corner
 + goes west on line E-W
 500 ft from line cut out in the map
 years ago.

Metal Location Poster is on a *Letter*
 tree $\frac{1}{2}$ inches diameter, on the *North*
 side of _____
 from which this Corner bears _____
 chains distant.



(Make sketch of topography near Corner)