

U. S. Department of Agriculture

FOREST SERVICE

M-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24-25 W 4th Mer.

S 1/16 Corner common to sections 13, and 18

Corner consists of a Aspen post (not) in place State condition New

Dimensions above ground 3 x 4 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 13	N 1/16
T 58 N		S 18
R 25 W		T 58 N
		R 24 W
N	W	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

None

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO


If not, why? set by me this date by proportional measurement.

Seth H. Peterson (Signature)

5/21/58 (Date)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree 7 inches diameter, on the
 Metal Location Poster is on a **Aspen**



(Make sketch of topography near Corner)