

**U. S. Department of Agriculture**  
**FOREST SERVICE**

G-25

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 58N. R. 29W. 9th. Mer.

1/4 Corner common to Sections



, 12, and 7

Corner consists of a 6" scribed post (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

**CARDINAL POSITION****DIAGONAL POSITION**

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Yellow Pine

Diameter 8"

Bearing N 33° W

Distance 71 ks.

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? B.T. does not match with

original notes.

Arthur J. Johnson

(Signature)

Special Foreman

(Title)

2/26/40

(Date)

(Make sketch of topography near Corner)

	Sec.		Sec.
	Sec.		Sec.

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant. Give any further facts which will aid in finding this Corner again.

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

6-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R24&25W 4th Mer.

1/4 Corner common to Sections

13, and 7

Corner consists of a 6" Scipid Post (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	45.12		45.7
	T58N		T58N
	R25W		R24W
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 512			
BT			

Species Fallen Tree

Diameter 0"

Bearing N330W

Distance 7/ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? BT does not match with G.L.O. notes

Arthur J. Johnson

(Signature)

2/26/40 (Date)

Special Forester (Title)

(Make sketch of topography near Corner)

	Sec.		Sec.
	Sec.		Sec.

T. R. Mer.

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.  
Give any further facts which will aid in finding this Corner again.

U. S. Department of Agriculture  
FOREST SERVICE

G-75

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24-25 W 4th P. Mer.

1/4 Corner common to sections

7, and 12  
Corner consists of a Iron pipe & Cedar post in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		1/4
	S 12		S 7
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 12	1/4 S 7		
BT			

Species Cedar

Diameter 9

Bearing N 40° W

Distance 0.06 ch

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Reestablished by county

Surveyor about 1915


Seth W. Peterson  
(Signature)

5/12/38  
(Date)

Jr. Asst. to Tech.  
(Title)

(Make sketch of topography near Corner)

T. 58 N. R. 24-25 W. 4th P. Mer.



Metal Location Poster is on a

Aspen

tree 4 inches diameter, on the Northwest east

side of Creek

from which this Corner bears N 31° W

0.78

chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is in swamp. Willow and

Alder brush. Several Cedar and

Pemaseck stumps.

New corner post set same scribbling

as old corner post. Post is 4x4x36"

and is aspen.