

U. S. Department of Agriculture  
FOREST SERVICE

E-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24-25 W 4th p Mer.

section Corner common to sections

1, 2, 6, and 7

Corner consists of ~~iron pipe & post~~ <sup>Aspen</sup> in place



State condition ~~post rotten~~ -- pipe good

Dimensions above ground pipe - 2 x 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

scribed  
twice

BT S 7	T58N R25W S 12	S 1	T 58 N R 24 W S 6
-----------	----------------------	-----	-------------------------

BT	BT	BT	BT
----	----	----	----

Species R. Pine Stp. Balsam R. pine Stp. W. Pine  
Diameter 28 16 18 12

Bearings S 24° E S 27° W N 36° W N 35° E

Distance 0.45 ch 0.28 c 0.13 ch 0.33 ch

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? Reestablished by County  
Surveyor about 1915.


Seth W. Peterson  
(Signature)

5/13/38  
(Date)

Jr. Asst. to Tech.  
(Title)

T. 58 N. R. 24-25 W. 4 th P. Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a Aspen

tree 5 inches diameter, on the west

side of 12 white pine

from which this Corner bears S 29° E

0.25 chains distant.

Give any further facts which will aid in finding this

Corner again.

New Aspen 4 x 4 x 36" post set.

Same scribe as old post.