

U. S. Department of Agriculture

FOREST SERVICE

East McC
6000 L. McC

A-77

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 R. 25 Mer.

MC Corner common to Sections

5 - 32, _____, and _____

Corner consists of a I.P.P. (~~rock~~) in place

State condition good

Dimensions above ground 24' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Scrub</u>			

Species Cedar SP.

Diameter 10" 8"

Bearing S30E N30E

Distance 10' 25'

Do you believe this to be a genuine Land Office Corner? MS

If not, why? Set by county - 1954

Ralph P. Christopher
(Signature)

12-14-54
(Date)

D.F.R.
(Title)

Top middle for the

Pipe is 2 ft from west
Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears
2 ft side of

tree 10 inches diameter, on the west

Metal Location Poster is on a
Corner

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)