

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

A-12-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58-59 R. 25 Mer.

33-4 Corner common to Sections

M.C. on west side of, and wagon wheel hole

Corner consists of a Pipe-capped (not) in place


State condition good

Dimensions above ground 24" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch B1

Diameter 8 8"

Bearing SW NW

Distance 70' 35'

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No - set by county 1954

Ralph H. Christensen

(Signature)

12-14-54

(Date)

D. F. R.

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *West 10 FT*

side of

tree *4* inches diameter, on the *NE*

Metal Location Poster is on a *Bank*



(Make sketch of topography near Corner)

T. R. Mer.