

U. S. Department of Agriculture
FOREST SERVICE

Posted

~~Chippewa~~ NATIONAL FOREST J 4-5
CORNERS OF THE PUBLIC SURVEY

T. 58N R. 25W 4th Mer.

M.C. Corner common to Sections
7, and 18

Corner consists of a 5 IN ASPEN (not) in place
State condition good (IRON PIN)

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S 7	S 18		
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 7	S 18		
B.T	B.T		

Species W. Birch W Birch

Diameter 8 IN 8 IN

Bearing S 63° W N 20° W

Distance 17-1 20-1

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

9-5-34

(Date)

Field ass't

(Title)

M.C. STAKE 150N
 W. BANK OF RUBY
 LAKE 5 MILE TAKE
 ROAD 8.11 CHAINS
 W. OF COR.
 SECOND GROWTH
 ASPEN & BIRCH

Corner again.

Give any further facts which will aid in finding this


15-11N K5 chains distant.

from which this Corner bears N. 63° E

side of tree

tree 7 inches diameter, on the N.E.

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 58 N R. 25 W 7th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

J-45

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 25 W. 4th Mer.

M.C. Corner common to Sections
7, and 18

Corner consists of a 5 IN ASPEN (not) in place
State condition good (IRON PIN)

Dimensions above ground 2'-6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S. 7	S. 18		
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 7	S. 18		
B.T.	B.T.		

Species W. Birch W. Birch

Diameter 8 IN 8 IN

Bearing S. 63° W N 20° W

Distance 14-11 20-11

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Ervin Meagher

(Signature)

9-5-34

(Date)

Field assist

(Title)

second growth
aspens & Birch

13.8.11 chains W. of
5 mile large road

M.C. 15 ON W.B. AND
of Ruby Lake

Corner again.

Give any further facts which will aid in finding this


15-LINKS chains distant.

from which this Corner bears
N. 63° E

side of tree

tree 7 inches diameter, on the N. E

Metal Location Poster is on a
W. Birch



(Make sketch of topography near Corner)

T. 58 N. R. 25 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

T-4-5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 4 Mer.

M.C. Corner common to Sections

_____, _____, 7, and 18

Corner consists of a 5" Aspen ^{170° 15' N} (net) in place

State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 7	S 18		
--------	---------	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 7	S 18		
B f	B f		

Species W. B. Birch W. B. Birch

Diameter 8" 8"

Bearing S 62° W N 20° W

Distance 14 Lks 20 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Ervin Mcagher
(Signature)

Field Asst
(Title)

9-5-24
(Date)

