

Range copy

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

1-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26-27 4 Mer.

S. 1/16 on range line Corner common to Sections
31 T. 58 N. R. 26, and 36 T. 58 N. R. 27

Corner consists of a Tamarack (~~not~~) in place

State condition Good

Dimensions above ground 4x4 By 56 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	$\frac{1}{16}$		$\frac{1}{16}$
	31		36

N W S E

NW SW SE NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? 1/16 corner not in original survey.

Robt. Broadbridge

(Signature)

6/24/36

(Date)


FOREMAN OF SURVEY CREW

(Title)

W. W. M.

Metal Location Poster is on a **ASPEN** tree 8 inches diameter, on the west side of the line from which this Corner bears S. 20R. 66 chains distant. Give any further facts which will aid in finding this Corner again.

Iron pipe two inches above the ground.



(Make sketch of topography near Corner)

superior copy

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST Y1

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26-27 Mer. 4
S. 1/16 on range line Corner common to Sections

31 T. 58 N. R. 26, and 36 T. 58 N. R. 27.

Corner consists of a Pumuck in place
State condition Good

Dimensions above ground 424 By 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1		1
	16		16
	31		36
N	W	S	E

NW	SW	SE	NE

Mound of none is located

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? 1/16 corner not in original survey.

R. B. Woodbridge
(Signature)


6/24/30
(Date)

FOREMAN OF SURVEY

(Title)
W. H. M.

the ground.
Iron pipe two inches above
Corner again.
Give any further facts which will aid in finding this
chains distant.

from which this Corner bears
side of
the line
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)