

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted

Chippewa NATIONAL FOREST v1
 CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 26-27 W. 4th Mer.
 Sec. Corner common to Sections
 25, 36, 30, and 31

Corner consists of a 3" W. pine (not) in place
 State condition 1" iron pipe good

Dimensions above ground 3' high (6" high) inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
25	36	31	30
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 31	
		B.T	

Species *N. PINE STUMP*
 Diameter *14"*
 Bearing *S 47° E*
 Distance *79 Lks*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Emin Meagher
 (Signature)

12-17-34
 (Date)

Field Ass't
 (Title)

LAND VERY HILLY
HAZEL UNDER BRUSH
ON THE RIDGES

Corner again.

Give any further facts which will aid in finding this


79-115. ~~km~~ distant.

From which this Corner bears N 79° W

side of 56 AMP

tree 1/4 inches diameter, on the N.W.

Metal Location Poster is on a N. PINE STAMP



(Make sketch of topography near Corner)

T. 58 N. R. 26-27 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

1-12-34

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W (R7) 4th Mer.

Sec. Corner common to Sections
30, 31, 25, and 26

Corner consists of a 3" W. PINE (not) in place
State condition good ("iron pipe")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

		S	
		31	
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S	
		31	
		B.T	

Species _____ N. pine

Diameter _____ 1 1/4"

Bearing _____ S 44° E

Distance _____ 79 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Erwin Mueller
(Signature)

1-12-34
(Date)

Field Ass't
(Title)

Corner again.
LAND HILL scattered
STRIPES of HAZEL
Nelder brush

Give any further facts which will aid in finding this


79 M. chains distant.

From which this Corner bears N 49° W

side of tree

tree 1 1/4 inches diameter, on the N.W.

Metal Location Poster is on a N. PINE STAMP



(Make sketch of topography near Corner)

T. 58 N R. 26-27 W 4th Mer.

Form 274-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

V-101

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 26-27 W. 4th Mer.
 Sec. Corner common to Sections
 25, 26, 30, and 31

Corner consists of a 3" W. PINE (not) in place
 State condition 1" iron pipe good

Dimensions above ground 3' high [6" high] inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
25	36	31	30
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 31	
		BT.	

Species N. pine stump
 Diameter 14"
 Bearing S 77° E
 Distance 79-1 Ks

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Erwin Meagher
 (Signature)

12-18-34
 (Date)

Field Ass't.
 (Title)

LAND VERY HIGH
 HAZEL UNDER BRUSH
 ON THE RIDGES.

Corner again.


Give any further facts which will aid in finding this
 79 1/2 S. as distant.

From which this Corner bears N 40 W

side of tree

tree inches diameter, on the N.W.

Metal Location Poster is on a N. PINE STAMP



(Make sketch of topography near Corner)

T. 58 N. R. 26-27 W. 45 h Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26-27 W 4th Mer.

Sec. Corner common to Sections 25, 36, 30, and 31

Corner consists of a 3" W. pine (not) in place State condition 1" iron pipe good

Dimensions above ground 3' high (6" high) inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
25	36	31	30
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 31	
		B.T	

Species N. Pine stump
Diameter 14"
Bearing S 44° E
Distance 79 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Erwin M. ... (Signature)

12-13-34 (Date)

Field Ass't (Title)

LAND VERY HILLY
HAZEL & N. D. BRUSH
ON THE RIDGES

Corner again.

Give any further facts which will aid in finding this


79-1/2 ~~mi~~ distant.

from which this Corner bears N 49° W

side of tree

tree inches diameter, on the N.W.

Metal Location Poster is on a PINE STAMP



(Make sketch of topography near Corner)

T. 26N. R. 26W. 4th Mer.