

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 58 R. 26 4 Mer.

CS 1/16 # 12 Corner common to Sections  
31, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a Cedar 3 (not) in place


State condition Good

Dimensions above ground 36" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of none is located \_\_\_\_\_

Pits are located none

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Poster	N	0	N	E

Species Aspen

Diameter 5"

Bearing S. 20 W.

Distance .64

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

put in by Orron Juneau, Jr. Foreman

*O Juneau*

(Signature)

Chief Foreman

(Title)

6/26/36

(Date)


.....  
.....  
.....  
.....  
.....

Corner again. This 1/10 corner is three chains south of a lake on top of a high hill.

Give any further facts which will aid in finding this 64 chains distant.

from which this Corner bears S. 20 W. side of East side of line

tree 5 inches diameter, on the W. side of tree Metal Location Poster is on an Aspen



(Make sketch of topography near Corner)

Form 874-0—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Y  
-3



Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 25 Mer. 4  
52 1/16 (# 12) Corner common to Sections  
31, \_\_\_\_\_, and \_\_\_\_\_


Corner consists of a Corner (not) in place  
State condition Good

Dimensions above ground 30" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of None is located \_\_\_\_\_  
Pits are located None

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen  
Diameter 5"  
Bearing S. 20 W.  
Distance 64

Do you believe this to be a genuine Land Office Corner?  
If not, why?

Put in by ORSON J. JENSEN, JR. Foreman.

6/26/36 (Date) Orson Jensen (Signature)  
Const. Foreman (Title)

South of a lake on top of a high hill.


This 1/16 corner is three chains  
Corner again.

Give any further facts which will aid in finding this  
chains distant.

from which this Corner bears  
S. 20 E.

side of  
tree 3 inches diameter, on the  
East side of line  
S. side of tree

Metal Location Poster is on  
N. corner



(Make sketch of topography near Corner)

T. 20 R. 20 Mer.

**U. S. Department of Agriculture**  
**FOREST SERVICE**

*Chippewa* NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. 58 N R. 26 W 7 Mer.  
1/16 #12 #6 Corner common to Sections

-----, -----, 31, and -----  
Corner consists of a Cedar (not) in place  
State condition Good

Dimensions above ground 36 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>P. 184</u>		<u>NONE</u>	

Species ASPEN -----

Diameter 5" -----

Bearing S20W -----

Distance 64/ks -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

Put in by JUREAN

O. Jurean

(Signature)

J. F. Fisk

(Title)


6/23/26  
(Date)

T.

R.

Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a

*Aspen*  
*West*

tree 5 inches diameter, on the

side of

from which this Corner bears

*S 20° W*

chains distant.

*64*

Give any further facts which will aid in finding this

Corner again.

*3 chs 80. as a lake on top of a*  
*high hill*