

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST *E4*

CORNERS OF THE PUBLIC SURVEY

T. *58 N.* R. *26 W.* *9th.* Mer.

*E. 1/16* Corner common to Sections

*6*, and *7*

Corner consists of a *1" Iron Pipe* (not) in place


State condition

Dimensions above ground *6* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Aspen*

Diameter *12"*

Bearing *S. 92° W.*

Distance *105140*

Do you believe this to be a genuine Land Office Corner? *NO*

If not, why? *Records show it was set by County Surveyor.*

*H. Hamalainen*

(Signature)

*Enrollee*

(Title)

*11/17/90*

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


10

from which this Corner bears 5820 N

side of

tree 10 inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 50 N R. 26 W. 9th Mer.

copy

U. S. Department of Agriculture  
FOREST SERVICE

E-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 Mer.

1/16 Corner common to Sections

6, and 7  
Corner consists of a 1.00 nipped Poplar post (not) in place

State condition New

Dimensions above ground 4' + 4' + 40" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

APPROX 1/16 S 6		S 7 T. 58 R. 26 1/16	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


B. T. Species Aspen

Diameter 12"

Bearing S. 32 W

Distance 105 LKs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? County scribble on post

Harold Hamalainen

(Signature)

C. C. C.

(Date)

(Title)

Iron pipe 10" dia

Corner again.

Give any further facts which will aid in finding this


101K's chains distant.

from which this Corner bears N 22 E

side of of this street

tree 10 inches diameter, on the South

Metal Location Poster is on a Poplar



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 26 W. 9th Mer.

1/16 Corner common to sections  
6, and 7


Corner consists of a 1" Iron Pipe (  ) in place  
State condition

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 13"

Bearing S 32° W

Distance 105 lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County Surveyor

Harold Hamalainen  
(Signature)

11/17/40  
(Date)

Enrollee  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. *10*

from which this Corner bears *5230W*

side of

tree *10* inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

*T. 50N R. 26W* Mer. *4th*

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

B-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 1 Mer.

Corner common to Sections

....., ....., 6, and 7  
 Corner consists of a CEGAR POST - BROKEN OFF  
IRON PIPE (not) in place

State condition POST IS ROTTED.

Dimensions above ground PIPE 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		T56 R26 1/16 S7	
1/16 S6			
N	W	S	E

NW	SW	SE	NE

Mound of ..... is located .....

..... Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 Sec 7			
B.T.			

Species Aspen

Diameter 12"

Bearing S 32° W

Distance 105 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County scribbling on post


Harold Hamalainen  
 (Signature)

CCC  
 (Title)

(Date)

Corner again.  
Corner is on the west side  
of IT 541.

Give any further facts which will aid in finding this  
chain distant.  
From which this Corner bears N 22 E  
side of tree  
tree 1/8 inches diameter, on the  
Metal Location Poster is on a  
Aspen



(Make sketch of topography near Corner)

T 58 R 26 Mer.



U. S. Department of Agriculture  
FOREST SERVICE

E-4

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *58 N.* R. *26 W.* *4th* Mer.

*E. 1/4* Corner common to Sections  
*6*, and *7*

Corner consists of a *1" Iron Pipe* (~~rod~~) in place  
State condition

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *Aspen*

Diameter *12"*

Bearing *5.32° W.*

Distance *10.5 lks.*

Do you believe this to be a genuine Land Office Corner? *NO*

If not, why? *Records show it was set by County Surveyor*

*H Hamalair*

(Signature)

*Enallee*

(Title)

*11/17/90*

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. *10*

from which this Corner bears *5830 W*

side of

tree *10* inches diameter, on the

Metal Location Poster is on a *log*



(Make sketch of topography near Corner)

T. 58 N. R. 26 W. 4th Mer.