

2 amp  
copy

U. S. Department of Agriculture  
FOREST SERVICE

A-4

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4th Mer.

E 1/16

Corner common to Sections

6

, and Secs. 31, 59-26

Corner consists of a  cedar Post (not) ~~a~~ place



State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Aspen \_\_\_\_\_

Diameter 10" b \_\_\_\_\_

Bearing S 13 1/2 W N 16 50 E \_\_\_\_\_

Distance 12 lks 73 lks \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No


If not, why? County scribing on bearing trees. believe corner is in center of road

[Signature]  
(Signature)  
[Title]  
(Title)

10/22/36  
(Date)

located on south side of T. 591  
Timber type Hs pen - Balsam.  
Corner again.

Give any further facts which will aid in finding this  
12 Ms. ~~chain~~ distant.  
from which this corner bears Due South  
side of Post  
tree 6 inches diameter, on the north  
Metal Location Poster is on a F.S. Post



(Make sketch of topography near corner)

T. 59 N R. 21 W 4th Mer.

Form 874-9 Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

A-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>59</sup>58N R. <sup>26</sup>26W 4th Mer.  
E 1/16 Corner common to Sections  
\_\_\_\_\_, \_\_\_\_\_, \_\_\_\_\_, and 31

Corner consists of a Cedar Post (not) in place  
State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ASPEN ASPEN

Diameter 10" 6

Bearing S 13 1/2 W N 16 S E

Distance 12 LKS 73 LKS

Do you believe this to be a genuine Land Office Corner? No

If not, why? COUNTY SUTHERLAND  
BEARING TREES BELIEVE CORNER  
IS IN CENTER OF ROAD

M + M  
(Signature)


10/22/26  
(Date)

Sr CLARKS  
(Title) F R A

Corner again.  
located on S. side of T. 591  
Timber type ASPEN - BALDWIN

Give any further facts which will aid in finding this  
chains distant.

12  
from which this Corner bears Due South  
side of Post  
tree 6 inches diameter, on the North  
Metal Location Poster is on a F. S. Post



(Make sketch of topography near Corner)