

U. S. Department of Agriculture
 FOREST SERVICE

 Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4 Mer.

S $\frac{1}{16}$ Corner common to Sections

_____, _____, 19, and 20

Corner consists of a Tamarack (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	$\frac{1}{16}$		$\frac{1}{16}$
--	----------------	--	----------------

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Poster			

Species Tamarack

Diameter 5

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Corner put in by JUNEAU

 OTTAV JUNEAU
 (Signature)

 6/26/36
 (Date)

 Jr. Foreman
 (Title)

Corner East of logging road

Corner again.

Give any further facts which will aid in finding this


of chains distant.

from which this Corner bears S 44 E

side of line

tree 8 inches diameter, on the East

Metal Location Poster is on a B.A.S. Road



(Make sketch of topography near Corner)

T. 58 N R. 26 W 4th Mer.