

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

0-9

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 26 W. 4 Mer.

S. 1/16 Corner common to Sections

4, and 5

Corner consists of a _____ (not) in place


State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Ernest J. Forman

(Signature)

7/11/36
(Date)

Jr. Forman
(Title)

Corner again.

Give any further facts which will aid in finding this


31 lks. chains-distant.

from which this Corner bears N 55 E

side of the line.

tree 6 inches diameter, on the East

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

109

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 33 R. 22 Mer.

Corner common to Sections 36, 35, and 34


Corner consists of a stone (not) in place
State condition good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of stone is located at the corner

Pits are located at the corner

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species oak

Diameter 12

Bearing N 45° E

Distance 10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

1/14/36
(Date)

Proctor
(Signature)

Foreman
(Title)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

D-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 36 W. 4 Mer.

92/30 Corner common to Sections
 _____, _____, and _____



Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

7/13/36
 (Date)

O. Lunan
 (Signature)
 J. H. [Signature]

2

Corner again.

Give any further facts which will aid in finding this


~~in the~~ bears distant.

from which this Corner bears N 55 E

side of ~~the line~~

tree inches diameter, on the ~~East~~

Metal Location Poster is on a ~~corner~~



(Make sketch of topography near Corner)