

Superior
copy

U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST P13
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4 Mer.

1/4 Corner common to Sections
20, and 21

Corner consists of a Tam 3" Post (not) in place



State condition New (Replaced)

Dimensions above ground 32 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Data taken from C.C. Survey Notes.

by P. B. CENTERWELL
(Signature)

7/15/37
(Date)

JAN. FORESTER
(Title)

I. C. MURBECK

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears $N 21^{\circ} E$


side of TR E

tree 4 inches diameter, on the SW

Metal Location Poster is on a T am

FOREST SERVICE

RECEIVED
JUL 19 1937
CASS LAKE MINN



(Make sketch of topography near Corner)

T. 58 N. R. 26 W. Mer. 4