

U. S. Department of Agriculture
FOREST SERVICE

N-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 4 Mer.

Section

Corner common to Sections

15, 16, 21, and 22

Corner consists of a Ironwood (not) a place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W Birch W.P.

Diameter 6" 36"

Bearing S 40 E N 40 E

Distance .05 ch. .14 ch.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner reestablished by County Survey.

(Signature)

(Date)

(Title)

Corner again. Alice, lunch, again, lunch.

Give any further facts which will aid in finding this


~~to~~ 05 chains distant.

from which this Corner bears S 44° W. 81 N 40' W

side of ~~the~~ tree.

tree ~~5~~ inches diameter, on the S W NW

Metal Location Poster is on a ~~W.F.~~ W. Birch



(Make sketch of topography near Corner)

T. 58 R. 76 Mer. 4

Boyer

U. S. Department of Agriculture
FOREST SERVICE

N-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24 W 4 m Mer.

Section Corner common to Sections

15, 16, 21, and 22

Corner consists of a Iron nail (not) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Birch W. Pine

Diameter 6" 36"

Bearing S40°E N44°E

Distance 5 Lks 14 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner re-established by

County Survey

Data taken from C.C. Survey Notes

by P. B. Carterwall

(Signature)

7/15/37

(Date)

John Forster

(Title)

I. C. Murbeck

Rolling Birch - aspen

Corner again.

Give any further facts which will aid in finding this


.05 chains distant.

from which this Corner bears *No 40 W*

side of Tree

tree 4 inches diameter, on the *NW*

Metal Location Poster is on a *N Birch*



(Make sketch of topography near Corner)

T. 58 R. 26 Mer. 4

U. S. Department of Agriculture

FOREST SERVICE

PP

Chippewa NATIONAL FOREST N 13
 CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4th Mer.

Section Corner common to Sections
 15, 16, 21, and 22

Corner consists of a Iron nail [?] fast (not) in place


State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Spruce W. Pine

Diameter 6" 36"

Bearing S 40 E N 44 E

Distance 5/ks 14/ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner re-established

by county survey

Data taken from CCC Survey Notes

by P. B. CENTERWALL

(Signature)

7/15/35


(Date)

JUN. FORESTER

(Title)

FOREST SERVICE

RECEIVED
JUL 19 1937
CLASS LAKE, MINN



(Make sketch of topography near Corner)

T. 58 R. 26 Mer. 4

Metal Location Poster is on a Birch tree 6 inches diameter, on the NW

side of Tree

from which this Corner bears

N 40° W

112.5 chains distant.

Give any further facts which will aid in finding this

Corner again.

Rolling land - Aspen & Birch