

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

proposed
C13

W. K. ... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 1 Mer.

1/4 Corner common to Sections

3, and 4

Corner consists of a Norway pine (not) in place

State condition good

Dimensions above ground 4x4x3.1 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4 S 4		1/4 S 3
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 3

--

1/4 S 3

--

BT

--

BT

--

Species Norway pine White pine

Diameter 5.00 2.00

Bearing E 20° N 10°

Distance .300 .200

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

S. ...

Signature.

Nov 14, 1933 ...

Date. Title. 8-3027

