

U. S. Department of Agriculture
FOREST SERVICE

N-17

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26 Mer.

Section Corner common to Sections
14, 15, 22, and 23

Corner consists of a scrub post (not) in place
State condition great & sound

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species No. 1

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why?


Ralph H. Christensen
(Signature)

2-20-57
(Date)

D. F. R.
(Title)

Corner again.
 Spaced 2 Trees - Bottom 8"-4" E of post
 Maple 10"-12" East of post
 Blazed line 2.6 - E - 5 - W
 Cut out transit line 2 dls South
 pretty well grown up
 Under north top of birch ridge
 On west side as shown on
 type map but 100 E out of map
 location

Metal Location Poster is on a *Map*
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

posted

CHIPPEWA NATIONAL FOREST N 17

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 Mer. 4


SECTION Corner common to Sections
15, 14, 22, and 23

Corner consists of a NEW stake (not) in place
 State condition NEW

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<u>WILLOW</u>	<u>WILLOW</u>	<u>MAPLE</u>	<u>BIRCH</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N 70° W</u>	<u>S 25° W</u>	<u>N 70° E</u>	<u>N 30° E</u>
Distance	<u>500'</u>	<u>700'</u>	<u>350'</u>	<u>200'</u>

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Old stake set at N. 20° W

Luke R. Maurin
 (Signature)

ESTIMATOR
 (Title)

11-14-33
 (Date)

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

N-17
posted

CHIPPEWA NATIONAL FOREST

~~23~~

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 S. 4 Mer.

SECTION Corner common to Sections
14, 15, 22, and 23

Corner consists of a Post (not) in place
State condition NEW

Dimensions above ground 36 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 15	S 22	S 23	S 14
---------	---------	---------	---------

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 15

--

S 23

S 14

BT

BT

BT

BT

Species	WILLOW	WILLOW	MAPLE	W. BIRCH
Diameter	6"	20"	10"	5"
Bearing	N 70° W	S 20° W	N 90° E	N 30° E
Distance	50 FT.	20 FT.	15 FT.	20 FT.

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Luke B. Martin
(Signature)

Estimator
(Title)

11-20-33
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

11-17

4

R. 26

T. 58