

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*Chap Unit*

NATIONAL FOREST 219

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 4 Mer.

1/4 Corner common to Sections

35 and 2  
Corner consists of a *high iron* (not) in place

State condition *good*

Dimensions above ground 41 x 36 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S		2	
35			


N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Y45
35




BT
----

--

--

--

Species *Poplar*

Diameter *8"*

Bearing *N45°E*

Distance *1 ch.*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*S. R. ...*

(Signature)

*Nov 15 1933*

(Date)


*Comptroller*

(Title)

*Sketch in sketch of  
of ground. A corner  
near*

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)