

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

oe-N

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W. 4th P.M. Mer.

E 1/16 Corner common to Sections
 _____, 14, and 23

Corner consists of a 4" Cedar & pipe ~~iron~~ iron in place

State condition Good

Dimensions above ground 42" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

E 1/16		E 1/16	
S		S	
14		23	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16	E 1/16		
S 23	S 14		
BT	BT		

Species Birch Stub, Birch Stub

Diameter 8" 7"

Bearing S 37° E N 24° W.

Distance 16 Lks. 8 1/2 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Big L. L. L. L.
 (Signature)

11/12/36
 (Date)

S. F. P.
 (Title)

In Balsam swamp - light brush.
Corner again.

Give any further facts which will aid in finding this

chains distant.


0.16

from which this Corner bears N 37° W.

side of hill.

tree 8 inches diameter, on the N

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

N-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T 58N. R. 26W. 4th P.M. Mer.

E1/16 Corner common to Sections 14, and 23

Corner consists of a 4" Cedar & pipe in place



State condition Good

Dimensions above ground 42" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Stub, Birch Stub

Diameter 8" 7"

Bearing S37° E N24° W

Distance 16 Lks. 8 1/2 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Signature of Sig. Halgaard

(Signature)

G. A. P.

(Title)

11/12/36

(Date)

Corner again.
In Balsam swamp - light brush.

Give any further facts which will aid in finding this


0.16 chains distant.

from which this Corner bears N37°W

side of hill.

tree 8 inches diameter, on the N

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)