

U. S. Department of Agriculture  
FOREST SERVICE

1-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 W 4th p Mer.

section Corner common to sections

25, 26, 35, and 36

Corner consists of a Aspen post (not) in place



State condition New

Dimensions above ground 3 1/2 x 3 1/2 x 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 58 N  
R 25 W  
S 26

scribing  
unlegible

scribing  
unleg.

BT

Species Balsam Aspen Aspen

Diameter 8 9 7

Bearing N 9° E S 59° W S 21° E

Distance 26 7 20

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Reestablished by County

Surveyor

Seth W. Peterson


(Signature)

5/23/38 (Date)

Jr. Asst. to Tech. (Title)

Corner again.  
 Give any further facts which will aid in finding this  
 Corner is on south side of beaver  
 flowage/ BT and WT stand on edge of  
 water. Old stake rotted down.  
 New one has same scribbling.

0.31 chains distant.  
 from which this Corner bears  
 S 27° W  
 side of Balsam BT  
 tree 7 inches diameter, on the East  
 Metal Location Poster is on a White Spruce



(Make sketch of topography near Corner)

T. 58 N R. 25 W 4th P Mer.