

Ranger com

U. S. Department of Agriculture  
FOREST SERVICE

T-252

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W 42 Mer.

1/16 #1 Corner common to Sections

30, and 25 57-27

Corner consists of a Cedar Post 5" (not) in place


State condition good

Dimensions above ground 36 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Red Spruce Cedar

Diameter 4" 8"

Bearing S84°W N51°W

Distance 25 lks 66 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? County resurvey corner

Data taken from CCC survey notes

H. P. B. Centerwall

(Signature)

7/15/37  
(Date)

Jun Forester  
(Title)

*no metal location post  
found up yet*

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.