

U. S. Department of Agriculture  
 FOREST SERVICE

 Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25 &amp; 26 4th Mer.

 Section Corner common to Sections  
 12, 13, 7, and 18

Corner consists of a \_\_\_\_\_ (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

R. 26	R. 25
S	S
12	13
NW	SW
SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

 Sketch markings of Bearing Trees (or Rocks) in proper box and  
 fill blanks below, giving bearings from Corner to Trees and  
 Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Ervin Meagher


(Signature)

9-4-34

(Date)

Field Ass't

(Title)



T. 58 N R. 25 E 26 4th Mer.  
 (Make sketch of topography near Corner)

Metal Location Poster is on a **ASPEN** tree **4** inches diameter, on the **N.E.** side of **tree**

from which this Corner bears **N. 41° E.**

**21-1/2** chains distant.

Give any further facts which will aid in finding this

Corner again.

**Cor. stake is on W. side of large dead**  
**tree S.W. corner**  
**N.O.B.T.**

U. S. Department of Agriculture  
FOREST SERVICE

J-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 25-26 4 Mer.

Section Corner common to Sections  
12, 13, 7, and 18

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

R 26	3	R 25	5
5		9	
12	13	18	7

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Ervin Mangor

(Signature)

Field Asst

(Title)

9-4-24  
(Date)


-----  
-----  
-----  
-----  
-----

Corner again.  
ON NW side of large dead  
Lam. Swamp No. BT

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of tree  
tree 4 inches diameter, on the  
Metal Location Poster is on a

N 41° E

45.22 N



(Make sketch of topography near Corner)