

U. S. Department of Agriculture
FOREST SERVICE

FAG-13
15-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4th Mer.

..... Meander Corner common to Sections

....., 9, and 10

Corner consists of a 4" N. PINE (~~not~~) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 9		
	BT		

Species N. PINE

Diameter 14"

Bearing S 68° W

Distance 24 LKS

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

.....

.....

FRANK MEAGHER

(Signature)

9-12-24

(Date)

Field Ass't

(Title)

Handwritten notes on a ruled page, including the phrase "side of lake" written upside down.

2nd grant N. Pike on S.E. side of lake

Corner again.

Give any further facts which will aid in finding this


3/ chains distant.

from which this Corner bears S 81° E

side of tree

tree 8 inches diameter, on the E

Metal Location Poster is on a N. Pike



(Make sketch of topography near Corner)

T. 58 N. R. 21 W. 4 Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

Ervin Meagher

T. 58 N. R. 26 W. 4th Mer.

M.C. Corner common to Sections

9, and 10

Corner consists of a 4 in. N. pine (not) in place

State condition good

Dimensions above ground 3 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

	S 9	S 10	
--	--------	---------	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 9		
	B.T.		

20
9-10-15

Species N. pine

Diameter 1 1/4 in.

Bearing S. 68 W

Distance 27 li.

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

Ervin Meagher

(Signature)

9-12-34

(Date)

Field Ass't

(Title)

Small stand of
second growth N. pine
on S.E. side of lake

Corner again.

Give any further facts which will aid in finding this


31-11! ~~eterns~~ distant.

From which this Corner bears S 81° E

side of tree

tree 8 inches diameter, on the

Metal Location Poster is on a N. pine



(Make sketch of topography near Corner)

T. 58 N R. 26 W 4th Mer.