

U. S. Department of Agriculture  
FOREST SERVICE

*Pratt*  
Chippewa NATIONAL FOREST W-X13

CORNERS OF THE PUBLIC SURVEY

T. 58N. R. 26W. 4<sup>1/2</sup> Mer.

M.C. Corner common to Sections

33, and 34.

Corner consists of a 4" W. birch post (not) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 33		S 34
--	---------	--	---------

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 33		S 34
			B.T.

Species Spruce

Diameter 4"

Bearing S. 8° E.

Distance 12 links

Do you believe this to be a genuine Land Office Corner? yes.

If not, why? Note: Found old gov. B.T.

With scribing plainly visible and re-estb. temp. post by referring to gov. field notes.

*Ernest Perry*  
(Signature)

10-8-34


(Date)

Field ass.

(Title)

Corner is located on S.E. bank of bay bearing N.W. & S.E. This bay is part of Kremen Lake.  
Corner again.

Give any further facts which will aid in finding this  
...~~11.111h3. chains distant.~~  
from which this Corner bears N.35°E.  
side of ... tree.  
tree ... 5 inches diameter, on the N.E.  
Metal Location Poster is on a W. birch



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

116X-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N. R. 26W. 4<sup>th</sup> Mer.

M.C. Corner common to Sections  
33, and 34

Corner consists of a 4" W. birch post (not) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S. 33		S. 34
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S. 33		S. 34
			B.T.

Species Spruce  
Diameter 4"  
Bearing S. 8° E.  
Distance 12 links

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Note: Found old gov. B.T. with scribing plainly visible and re-estb. temp. post by referring to gov. field notes.

Ernest Perry

(Signature)

10-8-34


(Date)

Field ass't

(Title)

Corner again.  
 Corner is located on S.E. bank of bay bearing NW  $4^{\circ}$  Mer. This bay is part of Kite Mer. Lake.

Give any further facts which will aid in finding this  
 11 links, ~~chain distant~~  
 from which this Corner bears N.  $35^{\circ}$  E side of ~~tree~~  
 tree 5 inches diameter, on the N.E. Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

3-X-13

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 26 W 4 Mer.

M.C. Corner common to Sections  
33, and 34

Corner consists of a 4" N. Birch Post (not) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 33		S 34
--	---------	--	---------

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S 33		S 34
			BT

Species Spruce

Diameter 4"

Bearing S 8° E

Distance 12 lks.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? Found old govt B.T. marking visible & re-established temp. post, by re-fixing to govt. notes.

H. J. West Terry  
(Signature)

10-8-24  
(Date)

Field Asst  
(Title)

located on S. bank of bay  
bearing NW 1/4 SE. bay part of  
Kramer Lake

Corner again.

Give any further facts which will aid in finding this


1/1 chains distant.

from which this Corner bears N 35. E

side of tree

tree 5 inches diameter, on the NE

Metal Location Poster is on a W. 1/4 S. 34



(Make sketch of topography near Corner)

**U. S. Department of Agriculture**  
**FOREST SERVICE**

10-X-1-W

*Chippewa* NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. *58N* R. *26W* *4<sup>th</sup>* Mer. *W*

..... *M.C.* Corner common to Sections  
....., *33*, and *34*.....

Corner consists of a *4" aspen post* (not) in place  
State condition *good*

Dimensions above ground ..... *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

**CARDINAL POSITION**

**DIAGONAL POSITION**

	<i>S.</i> <i>33</i>		<i>S.</i> <i>34</i>
N	W	S	E

NW	SW	SE	NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<i>S.</i> <i>33</i>		<i>S.</i> <i>34</i>
	<i>B.T.</i>		

Species ..... *N. pine* .....

Diameter ..... *8"* .....

Bearing ..... *N. 15° W.* .....

Distance ..... *2.5 links* .....

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? *Note: Found old gov. B.T. with scribing plainly visable and re-estb. temporary post by referring to gov. field notes.*

*Ernest Perry*

(Signature)

*Field visit*

(Title)

*10-15-34*  
(Date)

MC is located on north  
bank of small bay of  
Kremet Lake.

Corner again.

Give any further facts which will aid in finding this


511 mtrs. chains distant.

from which this Corner bears S.82.E.

side of tree

tree 4 inches diameter, on the SE

Metal Location Poster is on a aspen



(Make sketch of topography near Corner)