

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 4 Mer.

1/16 Corner common to Sections
30, and 31

Corner consists of a cedar post 3" - iron 8" (net) in place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species N.P.

Diameter 8"

Bearing N 19° W

Distance 53.1ks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? County reservoir

Data taken from C.C.C. Survey notes

H. P. B. Centurwall

(Signature)

7/15/37

(Date)

J. C. Forester

(Title)

J. C. Munkit

Corner again. Give any further facts which will aid in finding this


chains distant. 31

from which this Corner bears S 37° W

side of T x R

tree 4 inches diameter, on the SW

Metal Location Poster is on a A.S.P.N.



(Make sketch of topography near Corner)