

Superior copy

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Manuel

45

Shogawa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 4 Mer.

1/16 Corner common to Sections  
30, and 31



Corner consists of a 3 1/2" cedar post - 1 1/2" x 1 1/2" (not) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NP  
Diameter 8"  
Bearing N 17° W  
Distance 53 1/2

Do you believe this to be a genuine Land Office Corner? no

If not, why? County Resurvey

Data taken from CCC Survey Notes

by P. B. Centexwall

(Signature)

7/15/37  
(Date)

J. Forester

(Title)

I. C. Musbeck

