

U. S. Department of Agriculture

FOREST SERVICE

05

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 Y Mer.

S 1/16 # 14 Corner common to Sections

Corner consists of a 29, and 30. 3 1/2" Cedar + pipe (not) in place


State condition good

Dimensions above ground 36" post piped inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NP

Diameter 8"

Bearing N 19° W

Distance 53 cl.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Survey.

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

31


from which this Corner bears S 39° W

side of

tree 4 inches diameter, on the

*Maple*

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 58 R. 27 Mer.