

U. S. Department of Agriculture

FOREST SERVICE

7-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 4 Mer.

~~30~~ 1/4

Corner common to Sections

29, and 30

Corner consists of a W. Cedar 3 1/2" (not) in place

State condition good

Dimensions above ground 30 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Maple Snag

Diameter 6"

Bearing S 41° W

Distance 65 ch.

Do you believe this to be a genuine Land Office Corner? No

If not, why? County resurvey


(Signature)

(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 58 R. 27 Mer. 7