

U. S. Department of Agriculture
FOREST SERVICE

E-10

chipewand

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N, R. 27 W 4th Mer.

Section
4, 9

Corner common to Sections
, and

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T58N
R27W
S9

--

--

--

BT

--

--

--

Species Spruce

Diameter 17"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. O. Fredrickson

(Signature)

Forester (Admin)

(Title)


3/28/55
(Date)

Corner again.

Give any further facts which will aid in finding this

~~original bearing~~
 from which the corner bears
 tree 6513 NW 6 feet
~~original bearing~~

side of it
 tree 8" inches diameter, on the
 Metal Location Poster is on a
 Tamarack
 North



(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4th Mer.