

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

E13

T. 58N R. 27W 4 Mer.

8 Corner common to Sections
3, 4, 9, and 10

Corner consists of a _____ (not) in place


State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

Species Spruce

Diameter 4"

Bearing 831W

Distance 0.87

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Poole

(Signature)

3-28-35

(Date)

ccc Enrollee

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.87

from which this Corner bears N31E

side of Tree

tree inches diameter, on the NE

Metal Location Poster is on a Spruce (BT)



(Make sketch of topography near Corner)

T. 58N R. 27W 4 Mer.

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 27W 4 Mer.

8 Corner common to Sections
3, 4, 9, and 10

Corner consists of a _____ (not) in place


State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT			

Species Spruce

Diameter 4"

Bearing S31W

Distance 0.87

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Poole

(Signature)

3-28-35

(Date)

CCC Enrollee

(Title)

Corner again.

Give any farther facts which will aid in finding this


chains distant. 0.87

from which this Corner bears N31E

side of Tree

tree 4 inches diameter, on the N31E

Metal Location Poster is on a Spruce (BT)



(Make sketch of topography near Corner)

T. 58N R. 27W Mer. 4

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-13

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 27 W. 7 Mer.
5 Corner common to Sections
3, 4, 9, and 10



Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SPRUCE

Diameter 4"

Bearing S31W

Distance 0.87

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. Poole
(Signature)

7-20-35
(Date)

C.C.C. Enrallee
(Title)

Corner again.

Give any further facts which will aid in finding this


0.87 chains distant.

from which this Corner bears N 31 E

side of trees

tree 4 inches diameter, on the NE

Metal Location Poster is on a Spruce (BT)



(Make sketch of topography near Corner)

T. 58N R. 27W 4 Mer.