

Maxwell
Rgn. Sta.
copy

U. S. Department of Agriculture
FOREST SERVICE

A-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58⁵⁹ N., R. 27 W. 4th Mer.

E 1/16 Corner common to sections

34, and 3

Corner consists of a 1" iron pipe (not) in place

State condition good - has scribed guard stake

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/16		1/16
	S		S

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

6 S			
--------	--	--	--

			T
--	--	--	---

Species Balsm Millard Birch

Diameter 14" 16"

Bearing N17°W S21°W

Distance 0.28 chs. 0.24 chs.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by county

surveyors, evidently.

Charles J. Knoblauch

(Signature)

July 23, 1937

(Date)

Junior Forester

(Title)

All that remains of Buck B.T. is noted stump.


We set a 4" cedar guard stake, painted white, 30" high. Aspen tree with metal poster has two layers facing corner.

Corner again. Give any further facts which will aid in finding this

chains distant. 0.17

from which this Corner bears S77°E

side of tree inches diameter, on the SE Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 58 N., R. 27 W., 4th Mer.

Ray Lake copy

U. S. Department of Agriculture
FOREST SERVICE

A-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ⁵⁹58 R. 27 W. 4th Mer.

E 1/16 Corner common to Sections

34, and 3

Corner consists of a 1" iron pipe (not) in place

State condition good - has scribed guard stake

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/16</u>		<u>1/16</u>
	<u>S</u>		<u>S</u>

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

6
S

T

Species Balm Gilead Birch

Diameter 14" 16"

Bearing N 17° W S 21° W

Distance 0.28 chs 0.29 chs ©

Do you believe this to be a genuine Land Office Corner? No

If not, why? Evidently established by county surveyors.

Charles J. Knoblauch

(Signature)


Junior Forester

(Title)

July 23, 1927
(Date)

stump.
 All that remains of Birch B.T. is a rotten
 stump facing corner.
 Aspen tree with metal poster has two
 white, 30" high.
 We set a 4" cedar guard stake, painted
 corner again.

Give any further facts which will aid in finding this
 chains distant.
 0.17
 from which this Corner bears S 77° E
 side of tree.
 tree 6 inches diameter, on the SE
 Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)