

U. S. Department of Agriculture

FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 27W. 4th P.M. Mer. 1/4

Corner common to Sections

14, and 23

Corner consists of a 4" Aspen & pipe (not) in place

State condition Good

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4 S 14		1/4 S 23	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	1/4 S 14		

Species Maple  
 Diameter 14"  
 Bearing N 42° W.  
 Distance 42 Lks.


Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

*Sig. F. P.*  
 (Signature)  
 G. F. P.  
 (Title)

11/12/36 (Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a Maple

tree 14 inches diameter, on the E

side of hill.

from which this Corner bears S 42° E

0.42

chains distant.

Give any further facts which will aid in finding this

Corner again.

land slopes toward N.W. - road about

4 chs. W.

Rangers  
copy

U. S. Department of Agriculture  
FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 38 N R. 27 W 4 P.M. Mer.

Corner common to Sections  
14, and 23

Corner consists of a 4" Asbest Pipe (not) a place  
State condition good

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

4 S 14		4 S 23	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	4 S 14		

Species Maple

Diameter 14"

Bearing N 42° W

Distance 42 lks.

Do you believe this to be a genuine Land Office Corner? no

If not, why? Probably County corner.

Does not agree with G. L. O. notes.

Leonard Peterson

(Signature)

11/12/36

(Date)

CCC

(Title)

Corner again.  
 Give any further facts which will aid in finding this

Land slopes toward NW road  
 about 4 chs. W.


0.42 chains distant.

from which this Corner bears S 42° E

side of

tree 14 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

## U. S. Department of Agriculture

FOREST SERVICE

Coted

Chippewa NATIONAL FOREST N 19

## CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4th Mer.

1/4 Corner common to Sections

14, and 23

Corner consists of a 4" Cedar (cut) in place

State condition good (1/2" IRON PIPE 6")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 14		S 23	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 14		S 23	
B.T.		B.T.	

Species Basswood Maple

Diameter 14" 10"

Bearing N 65° E N 33° W

Distance 33 li 51 li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Emin Meagher

(Signature)

Field Ass't


(Title)

12-10-34

(Date)

Land level, second  
ground level, second  
Corner again.

Give any further facts which will aid in finding this  
51 / 1' ~~obvious distant~~  
from which this Corner bears S 33° E  
side of tree  
Metal Location Poster is on a Maple tree 1/2 inches diameter, on the S. E.



(Make sketch of topography near Corner)

T. 58 N R. 27 W 4th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

N 1/2

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4th Mer.

1/4 Corner common to Sections  
14, and 23

Corner consists of a 4" cedar (not) in place

State condition good (1 1/2" iron pipe 6"

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
14		23	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S		S	
14		23	
B.T.		B.T.	

Species Basswood Maple

Diameter 14" 10"

Bearing N 65° E N 33° W

Distance 33 li 51 li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Erwin Meagher  
(Signature)

12-10-34  
(Date)

Field Ass't  
(Title)

LAND LEVEL SECOND  
GROWTH ASPEN

Corner again.

Give any further facts which will aid in finding this


51.11! ~~corners~~ distant.

from which this Corner bears S33° E

side of tree

tree 10 inches diameter, on the S. E

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4 24 Mer.