

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST V21

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4th Mer.

----- Section Corner common to Sections
25, 26, 35, and 36

Corner consists of a 4" spruce (not) in place
State condition good 1" iron pipe

Dimensions above ground post 30" pipe 6" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
26	35	36	25
NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 25
			BT

Species ----- N. pine stump
Diameter ----- 1.5"
Bearing ----- S. 1° W
Distance ----- 31 LKS.

Do you believe this to be a genuine Land Office Corner? YES

If not, why? -----

Ervin Meagher

(Signature)


12/18/34 Field Asst.

(Date)

(Title)

Corner again.
Land hilly, scattered
noway pine.

Give any further facts which will aid in finding this
33 km/2 chains distant.
From which this Corner bears S 4° W
side of tree
tree 12" inches diameter, on the S. W.
Metal Location Poster is on a Norway pine.



(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

10-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4th Mer.

Section Corner common to Sections
25, 26, 35, and 36

Corner consists of a 4" spruce (not) in place
State condition good 1" iron pipe

Dimensions above ground rest 30" pipe 6" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
26	25	36	25
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 25
			BT

Species _____ No. pine
Diameter _____ 15" stump
Bearing _____ S. 1° W.
Distance _____ 31 lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

Field Asst.

(Title)

12/18/34

(Date)

Land hills, scattered Norway pine

Corner again.

Give any further facts which will aid in finding this

33 Lks chains distant.

From which this Corner bears S. 4° W.

side of tree

tree 12 inches diameter, on the S. W.

Metal Location Poster is on a Norway Pine

	36	35	
		8c	
	25	26	

(Make sketch of topography near Corner)

T. 58 N. R. 27 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

R-2-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 27 W 4th Mer.

Section Corner common to Sections
25, 26, 35, and 36

Corner consists of a 4" spruce (not) in place
State condition good 1" iron pipe

Dimensions above ground post 30" pipe 6" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

S	S	S	S
26	35	36	25
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			S 25
			BT

Species _____ N. pine stump
Diameter _____ 15"
Bearing _____ S. 1° W.
Distance _____ 31 Lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

Field Asst.

12/18/34


(Date)

(Title)

Corner again.
Land hilly, scattered
Norway pine

Give any further facts which will aid in finding this
33 AKS. ~~obscure~~ distant.

From which this Corner bears 5.4° W
side of tree
tree 12 inches diameter, on the SW
Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)

T. 58 N R. 27 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

12-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 29 N R. 27 W 4 Mer.

5 Corner common to Sections
25, 26, 35, and 36

Corner consists of a _____ (not) in place



State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 36	S 35		
BT	BT		

Species Tam Tam

Diameter 7" 5"

Bearing S 90 E S 5 W

Distance 0.70 0.70

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Roy Lapiex
(Signature)

4-1-35
(Date)

C.C. Enrollee
(Title)

Corner again.

Give any further facts which will aid in finding this


0.70 chains distant.

from which this Corner bears N 40 W

side of tree

tree 7 inches diameter, on the NW

Metal Location Poster is on a 70m (BT)



(Make sketch of topography near Corner)

T. 59N R. 27W Mer. 4

U. S. Department of Agriculture

FOREST SERVICE

V-21

CHIPPENAW

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59th R. 27th Mer.

Corner common to Sections 25, 26, 35, and 36

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species 22 22

Diameter 2.0 5.0

Bearing 50° 50°

Distance 0.70 0.70

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. **0.70**

from which this Corner bears **40°**

side of **3100**

tree **7** inches diameter, on the **NE**

Metal Location Poster is on a **500 (100)**



(Make sketch of topography near Corner)