

U. S. Department of Agriculture
FOREST SERVICE

0-22

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY


T. 58 R. 27 Mer.
16 SW 1/16 Corner common to Sections
_____, _____, _____, and ✓

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Act. Spruce
Diameter 8"
Bearing NW
Distance 15' ?

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Probably


P. H. [Signature]
(Signature)

2-28-57
(Date)

D. F. R.
(Title)

Corner again.
Post on 5000m road west
516
Iron pipe reported to
be in wheel track at log
road & below ground.
Set by Mill Hays who
drew it down.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)