

U. S. Department of Agriculture

FOREST SERVICE

C-72

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 27 Mer.

Int. CW 446 Corner common to Sections
-----, -----, -----, and 1

Corner consists of a 5 inch post (not) in place


State condition poor - Iron pipe - good

Dimensions above ground ----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen -----

Diameter 16" -----

Bearing S 20 W -----

Distance 14' -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? Reason -----


B. D. Christopher
(Signature)

D. F. R.
(Title)

2-28-37
(Date)

Corner again.
 BT Topography
 Tag on road 1/2 ch. West
 Contact point on road to E
 Line located E-N + S
 Transit line N-S-E-W

Give any further facts which will aid in finding this
 30 FT chains distant.
 from which this Corner bears N 70 E
 side of
 tree 6 inches diameter, on the
 Metal Location Poster is on a E 1/2 m



(Make sketch of topography near Corner)